



Work Continues on Cedar Creek at Innsbrook Village Country Club

The NRCS (Natural Resources Conservation Service) continues their work along Cedar Creek on Innsbrook Country Club. Since the last email you received, the NRCS is “dewatering” the creek, that is drying it out so that the large equipment needed to dig out the creek can get into it. There have been a few problems with drying out the creek bed. The most annoying one is that they continue to find underground springs flowing below the surface. In the pictures you see, they are digging deep holes at strategic places to pool the water and then placing pumps in those holes to pump the water out and off the property through the large white pipeline. This problem has not prevented the NRCS from digging out the creek, though. In the dry areas, they are digging and as you see in some of the pictures hauling off the dirt in dump trucks. If you have been on the property, it’s exciting to see the work occurring. If you have not been to Innsbrook recently, try to schedule a trip here and see all that is going on.

